

QuestMark 1015 Water Based Epoxy Coating

Directions for Use:

- *For 1-2 coat system, we recommend either a mechanical scarification or acid etching.*
- *For higher build, we recommend a fine brush blast.*
- *Ensure all dirt, oil, dust, or other debris has been removed and surface is dry.*
- *Exact mixing ratio is necessary, so we recommend mixing the entire kit unless proper weighing equipment is available (See Technical Data Sheet for exact mix ratio).*
- *Mix thoroughly with slow-speed mixer until material is streak-free.*
- *Apply using a roller or brush.*
- *For cleanup, use PM solvent*

PLEASE NOTE: This product has a usable application time of 60-90 minutes once mixed.