

## QuestMark 3449 Clear Polyaspartic Coating

### Directions for Use:

- *Should be applied as a topcoat for suitable broadcast system.*
- *For best results, we recommend a fine brush blast to provide a suitable substrate.*
- *Ensure all dirt, oil, dust, or other debris has been removed and surface is dry.*
- *Mixing ratio is 1.5 parts A to 1 part B by volume. Standard kits are pre-measured for proper mixing.*
- *Mix thoroughly with slow-speed mixer until material is streak-free.*
- *Transfer to another pail and mix again.*
- *Can be applied using a roller or brush, or using a serrated squeegee and back rolling onto surface.*
- *For cleanup, use xylol.*

**PLEASE NOTE: This product has a usable application time of 23-33 minutes once mixed.**